

## **Case Study**

PHONE: 952.927.9215 FAX: 952.927.9224

EMAIL: sales@synecosystems.com WEB: www.synecosystems.com

# Wolf Lake MI

### Problem:

Prior to installation, the H2S levels outside the closed hatch, at this Pump Station, were near 50ppm when measured above the keyhole. The odor was significant, and affecting many residents nearby (including the township supervisor).

#### **Solution:**

A Syneco Systems Peacemaker® 4x4 Odor Control System, with our patented Converting & Polishing media was installed.

#### **Results:**

Within 2 minutes of starting the unit, the odor was gone and the exterior ppm was zero. The unit has been installed for more than a year, the exhaust readings from the Syneco blower are still reading zero, and there is no odor from the station.

